

Type	L #	Hits	Search Text	DBs	Time Stamp
1	IS&R	L1	0 ("6787941.pn.") .PN.	USPAT	2005/10/14 09:00
2	BRS	L2	1 "6787941".pn.	USPAT	2005/10/14 09:55
3	BRS	L3	52 (actuator adj arm) with (machining or machined)	USPAT; EPO; JPO	2005/10/14 10:25
4	BRS	L4	258 (actuator adj arm) with (machine or machining or machined)	USPAT; EPO; JPO	2005/10/14 10:35
5	BRS	L5	217 4 not 3	USPAT; EPO; JPO	2005/10/14 10:26
6	BRS	L6	185 5 and @ad<"20000331"	USPAT; EPO; JPO	2005/10/14 10:26
7	BRS	L7	44 (E-block or (E adj block)) with (machine or machining or machined)	USPAT; EPO; JPO	2005/10/14 10:36
8	BRS	L8	33 7 not (3 or 4)	USPAT; EPO; JPO	2005/10/14 10:36
9	BRS	L9	1015 (actuator with resonance)	USPAT	2005/10/14 11:17
10	BRS	L10	861 9 and (disk or drive)	USPAT	2005/10/14 11:16
11	BRS	L11	536 10 and @ad<"20000331"	USPAT	2005/10/14 11:17

Type	L #	Hits	Search Text	DBs	Time Stamp
1	IS&R	L1	0 ("6787941.pn.") .PN.	USPAT	2005/10/14 09:00
2	BRS	L2	1 "6787941".pn.	USPAT	2005/10/14 09:55
3	BRS	L3	52 (actuator adj arm) with (machining or machined)	USPAT; EPO; JPO	2005/10/14 10:25
4	BRS	L4	258 (actuator adj arm) with (machine or machining or machined)	USPAT; EPO; JPO	2005/10/14 10:35
5	BRS	L5	217 4 not 3	USPAT; EPO; JPO	2005/10/14 10:26
6	BRS	L6	185 5 and @ad<"20000331"	USPAT; EPO; JPO	2005/10/14 10:26
7	BRS	L7	44 (E-block or (E adj block)) with (machine or machining or machined)	USPAT; EPO; JPO	2005/10/14 10:36
8	BRS	L8	33 7 not (3 or 4)	USPAT; EPO; JPO	2005/10/14 10:36